

Approved for public release;  
distribution unlimited

NO A 074168

PASSAIC RIVER BASIN  
ROCKAWAY RIVER, MORRIS COUNTY  
MORRIS COUNTY  
NEW JERSEY

(15) DACW 61-77-3-00111

LEVEL II


ROCK RIDGE LAKE DAM

NJ 00178

Official Report (10) Warren A. Guzman

PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

(6) National Dam Safety Program.  
Rock Ridge Lake Dam (NJ 00178), Passaic  
River Basin, Rockaway River, Morris  
County, Morris County, New Jersey.  
Phase 1 Inspection Report.



THIS DOCUMENT IS BEST QUALITY PRACTICE  
THE COPY FURNISHED TO DDC CONTAINED A  
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT  
REPRODUCE GRAPHICALLY

DEPARTMENT OF THE ARMY

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania

DDC FILE COPY

1979  
17 812

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00178	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Rock Ridge Lake Dam Morris County, N.J		5. TYPE OF REPORT & PERIOD COVERED  FINAL
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s)  Guinan, Warren A., P.E.		8. CONTRACT OR GRANT NUMBER(s)  DACW61-79-C-0011 <i>in</i>
9. PERFORMING ORGANIZATION NAME AND ADDRESS Anderson-Nichols 6 Loudon Rd. Concord, NH 03301		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		12. REPORT DATE August, 1979
		13. NUMBER OF PAGES 50
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report)  Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES  Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Visual inspection Spillways National Dam Inspection Act Report Structural Analysis Safety		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		



REPLY REFER TO

DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE--2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

NAPEN-D

17 SEP 1979

Honorable Brendan T. Byrne  
Governor of New Jersey  
Trenton, NJ 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Rock Ridge Lake Dam in Morris County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Rock Ridge Lake Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure, as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 20 percent of the Probable Maximum Flood--PMF - would overtop the dam. The spillway is considered "inadequate" instead of "seriously inadequate" because dam failure resulting from overtopping would not significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. Within six months from the date of approval of this report, the owner should retain the services of a professional engineer qualified in the design and inspection of dams to accomplish the following:

NAPEN-D

Honorable Brendan T. Byrne

(1) Design and oversee procedures for removing trees and brush from the upstream slope, downstream slope and downstream toe area of the dam.

(2) Investigate the large soft wet area near the west abutment and design appropriate remedial measures.

(3) Inspect the downstream slope and toe of the dam after the trees, brush, and debris have been removed.

(4) Design and supervise repairs for the eroded areas on the upstream slope at the spillway training walls and at two locations between the spillway and the west abutment.

(5) Design repairs to the concrete spillway apron and areas of spalling and erosion on the weir and training wall.

(6) Provide a paved surface for the walkway on the dam crest.

(7) Establish grassy vegetation or other protective covering on the cleared slopes and remaining portions of the crest of the dam.

(8) Investigate the need to install an upstream valve on the low level outlet pipe to relieve constant pressure in the pipe in the embankment as it presently exists.

c. Within 30 days from the date of approval of this report, the owner should carry out the following remedial measures:

(1) Remove the raft floating against the upstream edge at the spillway crest.

(2) Check the condition of the dam periodically and monitor the seepage at the wet areas at the downstream toe until remedial measures are effected.

d. Within six months from the date of approval of this report, the owner should carry out the following additional remedial measures:

(1) Remove the two trees that have fallen into the discharge channel.

(2) Clear trees and brush on either side of the discharge channel.

(3) Establish a surveillance program for use during and immediately following periods of heavy rainfall, and also a warning program to follow in case of floodflow conditions or imminent dam failure.

NAPEN-D

Honorable Brendan T. Byrne

(4) Engage a professional engineer qualified in the design and inspection of dams to make a comprehensive technical inspection of the dam once every two years.


(5) Periodically operate the low level outlet valve to prevent silting and seizing by rust.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman James A. Courter of the Thirteenth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.


Sincerely,

  
JOEL T. CALLAHAN  
Lieutenant Colonel, Corps of Engineers  
Acting District Engineer

1 Incl  
As stated

Copies furnished:  
Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

John O'Dowd, Acting Chief  
Bureau of Flood Plain Management  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
ENC TAP	<input type="checkbox"/>
Unpublished	<input type="checkbox"/>
Justification	<input type="checkbox"/>
By _____	
Date _____	
Approved _____	
Dist	_____
A 	

ROCK RIDGE LAKE DAM (NJ00178)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 17 May 1979 by Anderson-Nichols and Company, Inc. under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Rock Ridge Lake Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure, as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 20 percent of the Probable Maximum Flood--PMF - would overtop the dam. The spillway is considered "inadequate" instead of "seriously inadequate" because dam failure resulting from overtopping would not significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. Within six months from the date of approval of this report, the owner should retain the services of a professional engineer qualified in the design and inspection of dams to accomplish the following:

(1) Design and oversee procedures for removing trees and brush from the upstream slope, downstream slope and downstream toe area of the dam.

(2) Investigate the large soft wet area near the west abutment and design appropriate remedial measures.

(3) Inspect the downstream slope and toe of the dam after the trees, brush, and debris have been removed.

(4) Design and supervise repairs for the eroded areas on the upstream slope at the spillway training walls and at two locations between the spillway and the west abutment.

(5) Design repairs to the concrete spillway apron and areas of spalling and erosion on the weir and training wall.

(6) Provide a paved surface for the walkway on the dam crest.

(7) Establish grassy vegetation or other protective covering on the cleared slopes and remaining portions of the crest of the dam.

(8) Investigate the need to install an upstream valve on the low level outlet pipe to relieve constant pressure in the pipe in the embankment as it presently exists.

c. Within 30 days from the date of approval of this report, the owner should carry out the following remedial measures:

(1) Remove the raft floating against the upstream edge at the spillway crest.

(2) Check the condition of the dam periodically and monitor the seepage at the wet areas at the downstream toe until remedial measures are effected.

d. Within six months from the date of approval of this report, the owner should carry out the following additional remedial measures:

(1) Remove the two trees that have fallen into the discharge channel.

(2) Clear trees and brush on either side of the discharge channel.

(3) Establish a surveillance program for use during and immediately following periods of heavy rainfall, and also a warning program to follow in case of floodflow conditions or imminent dam failure.

(4) Engage a professional engineer qualified in the design and inspection of dams to make a comprehensive technical inspection of the dam once every two years.

(5) Periodically operate the low level outlet valve to prevent silting and seizing by rust.

APPROVED: 

JOEL T. CALLAHAN

Lieutenant Colonel, Corps of Engineers  
Acting District Engineer

DATE: 



PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam:	Rock Ridge Lake Dam
ID Number:	Fed. ID No. NJ00178
State Located:	New Jersey
County Located:	Morris
Stream:	Denney Brook
River Basin:	Passaic
Date of Inspection:	May 17, 1979

ASSESSMENT OF GENERAL CONDITIONS

Rock Ridge Lake Dam is about 53 years old and in fair overall condition. It is small in size and is classified as Significant Hazard. The crest of the dam shows evidence of trespassing and is bare of vegetation. Large trees and brush are growing on the upstream and downstream slopes of the dam. Extensive erosion has occurred to the upstream slope next to the training walls on both sides of the concrete spillway, and in two locations on the right crest of the dam. A large soft wet area was observed at the downstream toe near the right abutment. Debris has been dumped on the downstream slope near the right abutment. The concrete spillway apron has an open and unsealed expansion joint. Erosion and spalling of the surface of the spillway is visible. Several drill holes have been made in the top surface of the spillway apron. The spillway can pass approximately 20 percent of the PMF and is inadequate.

It is recommended that the owner retain the services of a professional engineer, qualified in the design and construction of dams, to accomplish the following in the near future: remove trees, their root systems and brush from the upstream slope, downstream slope, and downstream toe area of the dam; investigate the soft wet area near the right abutment of the dam and design and implement appropriate remedial measures; inspect the downstream slope and toe of the dam after the trees, brush, and debris have been removed; design and implement repairs for the eroded areas on the upstream slope at the spillway training walls and westerly embankment; conduct a more detailed hydrologic and hydraulic analysis of the watershed, dam, and spillway, and design and implement appropriate

mitigating measures to provide adequate discharge capacity; repair the drill holes, eroded and spalled areas in the apron, weir, and spillway concrete; provide a paved surface for the walkway on the dam crest; establish grassy vegetation or other protective covering on the cleared slopes and remaining portions of the crest of the dam; and investigate the need to install an upstream valve on the low level outlet pipe to relieve constant pressure in the pipe in the embankment as it presently exists.

It is further recommended that the owner accomplish the following tasks as a part of operating and maintenance procedures: immediately, remove the raft floating against the upstream edge of the spillway crest; starting immediately, check the condition of the dam periodically until remedial measures are effected; starting soon, clear trees from the banks of the discharge channel and remove the two trees that have already fallen; in the near future, establish a surveillance program for use during and immediately following periods of heavy rainfall, and also a warning program to follow in case of flood-flow conditions or imminent dam failure. In addition, the owner should engage a professional engineer qualified in the design and inspection of dams to make a comprehensive technical inspection of the dam once every two years. This should be started in the near future. Starting soon, the low level outlet valve should be operated periodically to prevent silting and seizing by rust.

*Warren A. Guinan*

Warren A. Guinan, P.E.  
Project Manager  
New Jersey No. 16848



17 MAY 1979

OVERVIEW

ROCK RIDGE LAKE DAM

## CONTENTS

### PHASE I INSPECTION REPORT NATIONAL DAM SAFETY REPORT

ROCK RIDGE LAKE DAM N.J. NO. 440 FED ID NO. NJ00178

	<u>Page</u>
SECTION 1 PROJECT INFORMATION	
1.1 <u>General</u>	1
1.2 <u>Project Description</u>	1
1.3 <u>Pertinent Data</u>	2
SECTION 2 ENGINEERING DATA	
2.1 <u>Design</u>	5
2.2 <u>Construction</u>	5
2.3 <u>Operation</u>	5
2.4 <u>Evaluation</u>	5
SECTION 3 VISUAL INSPECTION	
3.1 <u>Findings</u>	6
SECTION 4 OPERATIONAL PROCEDURES	
4.1 <u>Procedures</u>	7
4.2 <u>Maintenance of Dam</u>	7
4.3 <u>Maintenance of Operating Facilities</u>	7
4.4 <u>Warning System</u>	7
4.5 <u>Evaluation of Operational Adequacy</u>	7
SECTION 5 HYDROLOGIC/HYDRAULIC	
5.1 <u>Evaluation of Features</u>	8
SECTION 6 STRUCTURAL STABILITY	
6.1 <u>Evaluation of Structural Stability</u>	10
SECTION 7 ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES	
7.1 <u>Dam Assessment</u>	11
7.2 <u>Recommendations/Remedial Measures</u>	11
FIGURES	
1. Regional Vicinity Map	
2. Essential Project Features	
APPENDICES	
1. Engineering and Experience Data	
2. Check List Visual Inspection	
3. Photographs	
4. Hydrologic Computations	
5. References	

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY INSPECTION PROGRAM  
ROCK RIDGE LAKE DAM  
U.S. #NJ00178 N.J. #440

SECTION 1  
PROJECT INFORMATION

1.1 General

a. Authority. Authority to perform the Phase I Safety Inspection of Rock Ridge Lake Dam was received from the State of New Jersey, Department of Environmental Protection, Division of Water Resources by letter dated 4 April 1979 under Contract No. FPM-39 dated 28 June 1978. This Authority was given pursuant to the National Dam Inspection Act, Public Law 92-367 and by agreement between the State and the U.S. Army Engineers District, Philadelphia. The inspection discussed herein was performed by Anderson-Nichols & Company, Inc. on 17 May 1979.

b. Purpose. The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to the safety of Rock Ridge Lake Dam and appurtenances based upon available data and visual inspection, and determine any need for emergency measures and conclude if additional studies, investigations and analyses are necessary and warranted.

1.2 Project Description

a. Description of Dam and Appurtenances. Rock Ridge Lake Dam is a 10-foot high, 235-foot long earthfill dam, built around 1926 and rebuilt in 1949. The downstream and upstream faces have 3H:1V slopes. The 40-foot long free overflow spillway is near the center of the dam. The crest of the spillway is capped by a concrete slab. Immediately downstream of the crest is a sloping spillway apron about 42 feet long. A 12-inch diameter concrete, low level outlet pipe is located left of center of the spillway and one foot above the downstream toe. The 2.5' x 2.9' valve box, located in the center of the spillway apron just downstream of the 1-foot pier of the service bridge, contains one 12-inch gate valve. The service bridge is constructed of steel beams with wooden deck and railing and is set on one concrete pier. It spans the spillway about one foot upstream of the spillway crest and about 1.8 feet above the crest. A dirt path extends along the dam crest from each end of the service bridge. Essential features of the dam are given in Figure 2.

b. Location. The dam is located in Morris County, New Jersey on Denney Brook, a tributary to the Rockaway River, approximately 1 mile northwest of Denville. It is at north latitude 40°54.6' and west longitude 74°27.9'. A location map is given in Figure 1.

c. Size Classification. Rock Ridge Lake Dam is classified as being "small" on the basis of storage at the dam crest of 174 acre-feet, which is less than 1000 acre-feet, but more than 50 acre-feet, and on the basis of its height of 10.2 feet, which is less than 40 feet, in accordance with criteria given in the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. Visual inspection of the downstream area and the breach analysis contained herein show that failure of Rock Ridge Lake Dam could possibly lead to the overtopping of Denney Pond Dam downstream and subsequent overtopping of Florence Avenue, leading to appreciable but not excessive damage to 2 houses just downstream of Florence Avenue. Loss of any lives is unlikely. Thus Rock Ridge Lake Dam is classified as Significant Hazard.

e. Ownership. The dam is owned by the Rock Ridge Community Club, Denville, New Jersey. The President, Kenneth McQueen, 31 Edgewater Drive, Denville, New Jersey, was contacted for information.

f. Purpose of Dam. The lake was originally designed and is currently used for recreational purposes.

g. Design and Construction History. Little information was disclosed regarding the original design and construction of the dam, which took place around 1926. The dam was repaired and spillway rebuilt in 1949 after a cloudburst caused failure of the dam in 1947. Plans are on file at New Jersey Department of Environmental Protection. Little information was disclosed regarding the reconstruction.

h. Normal Operational Procedures. Rock Ridge Lake Dam is operated for recreational purposes. The lake level is lowered every 2 to 3 years to repair docks.

### 1.3 Pertinent Data

#### a. Drainage Areas

Drainage Area - .87 square miles (See Appendix 4.)

Normal Water Surface - 17.4 acres (See Appendix 4 )

b. Discharge at Damsite

Maximum flood at damsite - unknown

Low level outlet at pool elevation - 7 cfs

Ungated total spillway capacity at maximum pool elevation - 579 cfs

c. Elevation (ft. above MSL)

Top Dam - 523.6 minimum point  
525.2 maximum point

Maximum pool-design surcharge ( $\frac{1}{2}$  PMF) - 525.1

Recreation pool - 521.1

Spillway crest - 521.1

Upstream portal invert low level outlet (from design plans) - 515.6

Downstream portal invert low level outlet -  
514.4

Streambed at centerline of dam - downstream - 513.4

Maximum tailwater (estimated) - 519

d. Reservoir (feet)

Length of maximum pool - 1920

Length of recreation pool - 1800

e. Storage (acre-feet)

Recreation pool - 174

Design surcharge ( $\frac{1}{2}$  PMF) - 251

Top of dam - 218

f. Reservoir Surface (acres)

Top dam - 17.6

Spillway crest - 17.4

g. Dam

Type - earthfill



Length - 235'

Height - 10.2'

Top width - 10<sup>+</sup><sub>—</sub>

Side Slopes - Upstream - 3H:1V  
Downstream - 3H:1V

Zoning - Clay fill on upstream side of spillway  
shown on plans.

Impervious core - none indicated on design plans

Cutoff - 1 foot thick concrete cutoff wall at downstream end of spillway indicated on design plans.

Grout curtain - none indicated on design plans

h. Spillway

Type - free overflow

Length of weir - 40' nominal, 39' effective length

Crest elevation - 521.1

U/S Channel - Rock Ridge Lake

D/S Channel - Denney Pond

i. Regulating Outlets

Type - One 12-inch part concrete and part cast iron  
low level outlet pipe.

Length - 72'<sup>+</sup><sub>—</sub>

Access - Concrete housing in center of concrete  
spillway apron just downstream of crest.

Regulating facilities - gate valve

## SECTION 2 ENGINEERING DATA

### 2.1 Design

No plans, hydraulic, or hydrologic design data for the original Rock Ridge Lake Dam are available. Plans, hydraulic and hydrologic data for the rebuilt part of the dam and the spillway are on file at the New Jersey Department of Environmental Protection. The plans show an earth-filled dam with a 40-foot long, 12-foot wide spillway, with 4 expansion joints. The spillway apron is shown to extend for 9 feet downstream of the crest. The valve box with 12-inch gate valve is shown on the plans in the center of the apron by the downstream edge. The 12-inch diameter low-level outlet pipe is shown to be cast iron, with an intake upstream of the spillway and an outlet just below the gate valve.

### 2.2 Construction

No recorded data concerning construction of Rock Ridge Lake Dam were disclosed. Reference data on file with the New Jersey Department of Environmental Protection indicate that the dam was repaired and spillway rebuilt in 1949. The current Rock Ridge Lake Association president stated that concrete was added to the spillway in 1978 to repair erosion and undermining.

### 2.3 Operation

No engineering data pertaining to operation of the dam were disclosed.

### 2.4 Evaluation

a. Availability. A search of the New Jersey Department of Environmental Protection files, contact with community officials and contact with the owner revealed a limited amount of recorded information. All disclosed information was retrieved.

b. Adequacy. Because of the limited amount of recorded data available, evaluation of this dam was based primarily on visual observations.

c. Validity. Parts of the recorded data reviewed did not agree with visual observations. Specific discrepancies are discussed in Sections 5.1 a. and 6.1 b.

### SECTION 3 VISUAL INSPECTION

#### 3.1 Findings

a. Dam. The crest of the dam appears to be used extensively as a footpath and is bare of vegetation. Large trees and a heavy cover of brush are growing on both the upstream and downstream slopes of the dam. Extensive erosion has occurred on the upstream slope next to the training walls on each side of the spillway and at two locations between the spillway and the west abutment. One large soft wet area was observed at the downstream toe near the right abutment. Brush, stumps, leaves, and grass clippings which have been dumped on the downstream slope of the dam near the west abutment and a very heavy growth of rose bushes, brush, and trees on the downstream slope and at the downstream toe of the dam make it impossible to inspect adequately for evidence of seepage along the entire length of the dam. A raft was floating against the upstream edge of the spillway crest.

b. Appurtenant Structures. The concrete spillway apron has an open and unsealed expansion joint. Several drill holes have been made in the top surface of the concrete middle apron of the spillway. The concrete weir and training wall exhibited evidence of minor spalling and surface erosion to a maximum depth of 1 inch. The concrete spillway apron appears to have been recently extended. The 12-inch low-level outlet pipe and valve appeared to be in fair condition but were not operated during the inspection. The service bridge beams and decking were in good condition.

c. Reservoir Area. The watershed above the dam is gently sloping and wooded. Slopes adjacent to the reservoir appear stable. Some homes and a bathhouse are located on the shore of the reservoir. No evidence of significant sedimentation was observed.

d. Downstream Channel. Two trees have blown over across the channel immediately downstream of the dam. Many trees overhang the area downstream of the dam.

## SECTION 4 OPERATIONAL PROCEDURES

### 4.1 Procedures

No formal operating procedures were disclosed. Water is lowered every 2 or 3 years for dock maintenance purposes.

### 4.2 Maintenance of Dam

No formal maintenance procedures for the dam were disclosed.

### 4.3 Maintenance of Operating Facilities

No formal maintenance procedures for the operating facilities were disclosed.

### 4.4 Warning System

No description of any warning system was disclosed.

### 4.5 Evaluation of Operational Adequacy

Because of the lack of operation and maintenance procedures, the remedial measures described in Section 7.2 b. should be implemented as prescribed.

## SECTION 5 HYDROLOGIC/HYDRAULIC

### 5.1 Evaluation of Features

a. Design Data. Design spillway capacity was based on "a 16K storm of 6 hours duration," which produced the maximum discharge for a 50-year storm. Several other durations were investigated. The peak inflow of 450 cfs was routed through the lake to obtain a peak outflow of 266 cfs. In a letter dated October 17, 1949 to Newell C. Harrison, Engineer for the owner, from H. T. Critchlow, Director and Chief Engineer for the State Division of Water Policy and Supply, a minimum freeboard of 2.5 feet is specified for a forty-foot long broad-crested spillway. Two hydraulic features of the structure did not agree with the original design plans. A one-foot wide concrete pier supports the service bridge which spans the spillway, and reduces the effective weir length to 39 feet and the freeboard to 1.8 feet. The downstream spillway apron was found to extend downstream about 42 feet. It appears that several downstream sections have been added to the spillway apron shown on the plans. The 12-inch low level pipe is concrete at its outlet. It is believed to be concrete pipe under the new spillway and is shown in the design plans to be cast iron pipe at the valve box. Engineering data are given in Appendix 1.

b. Experience Data. The original dam was overtopped and breached during a cloudburst on May 25, 1947. The peak inflow and frequency of the storm were not determined. The breach formed was about 30 feet wide by 30 feet long. Recorded descriptions are included in Appendix 1 and state that no significant property damage occurred. No experience data were disclosed regarding the current dam and spillway.

c. Visual Observations. No visual evidence was found of damage to the structure caused by overtopping. At the time of inspection, water less than one inch deep was passing over the spillway crest.

d. Overtopping Potential. The hydrologic/hydraulic evaluation of Rock Ridge Lake Dam is based on a spillway design flood (SDF) equal to one-half the probable maximum flood (PMF) in accordance with the range of test floods given in the evaluation guidelines for dams classified Significant Hazard and small in size. The PMF has been determined by application of the SCS dimensionless unit hydrograph to a 24-hour PMP storm of 22.5 inches. Hydrologic computations are given in Appendix 4. The routed half-PMF peak discharge for the subject watershed is 2,197 cfs.

The minimum elevation of the dam allows 2.4 feet of depth in the spillway before overtopping occurs. Under this head, the spillway capacity is 579 cfs, which is less than the required SDF.

Flood routing calculations indicate that Rock Ridge Lake Dam will be overtopped for four hours to a maximum depth of 1.5 feet, under half-PMF conditions. It is estimated that the dam can pass less than 20 percent of the PMF without overtopping, thus the spillway is considered inadequate.

Because the dam was initially classified as high hazard based on visual observation, a breach analysis was performed to assess the increase in downstream hazard under dam failure conditions. The results of breach analysis, contained in Appendix 4, show that the downstream hazard is not increased under dam failure conditions. The inundation at the potential damage area downstream is such that the hazard is more appropriately classified as Significant.

e. Drawdown Capacity. If the low level outlet is in operable condition, it is estimated that the pond can be drained in approximately 13½ days, assuming no significant inflow. This time period is considered marginal for draining the reservoir in an emergency situation.

## SECTION 6 STRUCTURAL STABILITY

### 6.1 Evaluation of Structural Stability

a. Visual Observations. The use of the crest of the dam as a footpath and the absence of vegetation on the crest could lead to serious erosion of the dam if not remedied. If the trees growing on the upstream and downstream slopes of the dam blow over and pull out their roots, or if a tree dies and its roots rot, serious seepage and erosion problems may result. Erosion of the upstream slope at the spillway training walls and at two other locations, if allowed to continue, may lead to breaching of the dam. The large soft wet area near the west abutment, if uncorrected, could lead to a stability problem in the future.

Based on the visual inspection alone it is not possible to determine the physical properties of the foundation soil or the character of the interior of the cross section. Therefore, it is not possible to evaluate the factor of safety of the dam against slope failure. The open and unsealed joint and the open drill holes in the spillway apron could lead to rapid deterioration and undermining of the concrete in the apron.

b. Design and Construction Data. A drawing dated 1950 indicates that the existing cross section of the dam consisted principally of a sand and gravel fill and an upstream slope of "riprap over clay." A concrete cutoff wall is shown to be under the concrete spillway apron several feet downstream from the downstream edge of the crest of the dam. No riprap was found on the upstream face of the dam during the inspection.

c. Operating Records. An inspection report dated June 2, 1947 indicates that "on Sunday night, May 25, a severe cloud-burst occurred in this section of Morris County, resulting in the overtopping of the dam and washing out a section of the dam about 30 feet wide."

d. Post-Construction Changes. After the May 25, 1947 breach the dam was reconstructed based on design data included in Appendix 1.

e. Seismic Stability. Rock Ridge Lake Dam is located in Seismic Zone 1 and in accordance with the recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7  
ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment

- a. Condition. Rock Ridge Lake Dam is 53 years old and in fair condition.
- b. Adequacy of Information. The information available is such that the assessment of the dam must be based primarily on the results of the visual inspection.
- c. Urgency. The recommendations made in 7.2 a. and the operating and maintenance procedures 7.2 c. should be implemented by the owner as prescribed below.
- d. Necessity for Additional Information. The dam should be inspected again after the trees, brush, and debris have been removed from the downstream slope and downstream toe area. The information available from the present visual inspection is adequate to identify the potential problems that are listed in Sections 5 and 6. These problems will require the attention of a professional engineer who will have to make additional engineering studies to design or specify remedial measures to rectify the problems. If left unattended, the problems could lead to instability of the structure.

7.2 Recommendations/Remedial Measures

- a. Recommendations. The owner should retain the services of a professional engineer qualified in the design and inspection of dams to accomplish the following in the near future:
  - (1) Design and oversee procedures for removing trees and brush from the upstream slope, downstream slope and downstream toe area of the dam.
  - (2) Investigate the large soft wet area near the west abutment and design appropriate remedial measures.
  - (3) Inspect the downstream slope and toe of the dam after the trees, brush, and debris have been removed.
  - (4) Design and supervise repairs for the eroded areas on the upstream slope at the spillway training walls and at two locations between the spillway and the west abutment.



(5) Conduct a more detailed hydrologic and hydraulic analysis of the spillway to determine the need and type of remedial measures necessary.

(6) Design repairs to the concrete spillway apron and areas of spalling and erosion on the weir and training wall.

(7) Provide a paved surface for the walkway on the dam crest.

(8) Establish grassy vegetation or other protective covering on the cleared slopes and remaining portions of the crest of the dam.

(9) Investigate the need to install an upstream valve on the low level outlet pipe to relieve constant pressure in the pipe in the embankment as it presently exists.

b. Operating and Maintenance Procedures. The owner should:

(1) Remove the raft floating against the upstream edge at the spillway crest. This should be done immediately.

(2) Check the condition of the dam periodically and monitor the seepage at the wet area at the downstream toe until remedial measures are effected. This should be started immediately.

(3) Remove the two trees that have fallen into the discharge channel. This should be done soon.

(4) Clear trees and brush on either side of the discharge channel. This should be done soon.

(5) Establish a surveillance program for use during and immediately following periods of heavy rainfall, and also a warning program to follow in case of floodflow conditions or imminent dam failure. This should be done in the near future.


(6) Engage a professional engineer qualified in the design and inspection of dams to make a comprehensive technical inspection of the dam once every two years. This should be started in the near future.

(7) Periodically operate the low level outlet valve to prevent silting and seizing by rust. This should be started soon.




MAP BASED ON STATE OF NEW JERSEY  
OFFICIAL HIGHWAY MAP AND GUIDE


Anderson-Nichols & Co, Inc.		U.S. ARMY ENGINEER DIST. PHILADELPHIA	
BOSTON		CORPS OF ENGINEERS	
MASSACHUSETTS		PHILADELPHIA, PA.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
ROCK RIDGE LAKE DAM			
LOCATION MAP			
TRIBUTARY TO ROCKAWAY RIVER		NEW JERSEY	
		SCALE: SEE BAR SCALE	
		DATE:	



ELEVATION



SPILLWAY SECTION



**PLAN**

Anderson - Nichols & Co, Inc BOSTON MASSACHUSETTS		U.S. ARMY ENGINEER DIST PHILADELPHIA CORPS OF ENGINEERS PHILADELPHIA, PA	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
ROCK RIDGE LAKE DAM			
ROCK RIDGE LAKE		NEW JERSEY	
		SCALE NOT TO SCALE	
		DATE JULY 1979	

APPENDIX 1

ENGINEERING AND EXPERIENCE DATA

ROCK RIDGE LAKE DAM

The required capacity of the spillway was determined as follows:

(1) The storm duration which would produce the maximum discharge for a storm of estimated 50-year frequency was determined by the approximate computations shown on Sheet #1, attached. A 16K storm of 6 hours duration, when routed through the lake, was shown to produce a maximum discharge over the spillway.

(2) Central Jersey curve run-off is estimated to represent the peak flow from a 15-year flood in this watershed. The ratio of a 6-hour duration, 50-year frequency flood to a 6-hour duration, 15-year frequency was estimated from the rainfall I-D curves to be 1.22. Thus, a 50-year flood peak is estimated at 436 c.s.m. (Central Jersey)  $\times 1.22 = 533$  c.s.m., or 450 sec. ft. By using 450 sec. ft. as the peak inflow into the lake during a 16K or 6-hour storm, an inflow hydrograph was plotted and the flood routed through the lake as shown on Sheet #2, attached.

The maximum discharge for this flood is 266 second feet.

DONE BY STATE WATER POLICY COMMISSION  
(see header on left of next page)  
DATE 1/10/50

NOTE: EXTENSIVE HYDROLOGIC COMPUTATIONS  
BACKUP IS ON FILE WITH  
N.J. DEP. IN MICROFICHE FORM.  
COPIES OF A QUALITY SUITABLE  
FOR REPRODUCTION WERE NOT  
OBTAINABLE AND THUS HAVE  
NOT BEEN INCLUDED IN THIS  
REPORT

STATE  
RIVER POLY  
COMMISSION

# ROCK RIVER LAKE - SUPPRESSION COMPUTATIONS, see Appl. 440 TO DETERMINE 50-YR. PEAK DISCHARGE

$K=22.5$  min,  $A=537$  ac-ft, SPILLWAY = 40 FT. LG,  $C=2.66$  SHEET 1 of 2

COMPUTED SPILLWAY CREST = ELEV. 98.00 CHECKER DATE 7/1/11 11/10 1550

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)
STORM DURATION	LAKE LEVEL OF INFLOW PEAK	CONGR. SPILLWAY	DISCH. VOL. UP TO INFLOW PEAK	STORAGE VOL. UP TO INFLOW PEAK	INFLOW VOL. UP TO INFLOW PEAK	TOTAL INFLOW VOLUME	INFLOW PEAK	SEE NOTE BELOW	SEE NOTE BELOW	DISCHARGE PEAK	LAKE LEVEL OF TIME OF MAX. DISCH.	RUN-OUT RAINFALL CORR. R.	TOTAL RAINFALL AC. FT.	TOTAL RAINFALL INCHES	AVERAGE RAINFALL IN/HR	CONGR. STORM PEAK	50-YR. DISCH.
2K	98.5	360	97	10.25	11.12	30.9	533	7.1	15.0	520	98.83	.30	1030	2.30	3.07	50	80
8K	99.2 99.5	138 145	98 104	24.16 25.17	33.96 35.59	77.3 80.9	536 562	24.8 26.0	40.0 41.5	223 233	99.60 99.71	46 60	168.0 176.0	3.76 3.94	1.25 1.3	45 55	229
16K	99.5 99.6 99.8	192 211 222	24.5 26.8 28.2	30.25 32.80 33.83	54.25 57.60 62.03	108.50 119.20 124.06	467 513 535	41.2 41.2 41.5	55.5 55.7 56.0	259 285 300	99.83 99.95 100.20	.60	181.0 192.0 207.0	4.24 4.4 4.53	.67 .74 .77	25 45 55	300
24K	99.65	222	41.9	33.83	75.73	140.0	418	54.0	65.0	372	99.90	.60	233.0	5.20			300

Notes:  
 Col. 4 - Computed at mean rate of discharge.  
 Col. 5 - Computed from Col. 6, using appropriate ratio shown on page 11 of section 13 of the code.  
 Col. 6 - Computed from Col. 6, using appropriate factor "C".  
 Col. 7 - Computed from Col. 6, using appropriate factor "C".  
 Col. 8 - Ratio of discharge rate at time of peak inflow to the peak inflow rate. Peak inflow rate determined from inflow hydrograph by extending discharge hydrograph to recession of peak.  
 Col. 9 - Ratio of peak discharge rate to the peak inflow rate. Peak inflow rate determined from inflow hydrograph by extending discharge hydrograph to recession of peak.  
 Col. 10 - Computed from Col. 8, using percent given in Col. 10.  
 Col. 11 - Estimated coefficient for various lengths of storm given in Col. 11.  
 Col. 12 - Di. of Col. 7 by coefficient in Col. 13.  
 Col. 13 - Rainfall in inches over entire area.  
 Col. 14 - Obtained from appropriate rainfall frequency curves.  
 Result - 16K storm has mid rate of discharge over spillway. Proceed with hydrograph routing.

Dam Application No. 110  
(25-191)State of New Jersey  
State Water Policy Commission

## REPORT ON DAM APPLICATION

To the State Water Policy Commission,  
State of New Jersey.

Gentlemen:

The application of William Wetmore, Rock Ridge Lake, Denville, N. J.

filed December 16, 1949 for approval of plans and for a permit to reconstruct a dam

known as Rock Ridge Lake on a small branch of the Rockaway River

situated in Denville, Morris County, New Jersey.

has been examined by Norman C. Wittwer, Principal Hydraulic  
Assistant-District Engineer.

## PRINCIPAL FEATURES

Location 25.1.1.7.1 ☒

Site inspected 9/21/49 - N.C.M.

Purpose of dam Summer colony

Length of dam 17½ feet

Drainage area 0.84 sq. mi.

Elevation of flow line 93.00 (Assumed H.A.M.)

Area of Lake 20.5 acres

Capacity of lake 162 MBL gals.

Type of dam Earth embankment

Top width 12 feet

Upstream slope 2:1 *irregular*

Downstream slope 2:1

Foundation material Unknown

Max. height 8.92 feet

Type of spillway Concrete broad-crested weir, C = 2.64

Length of spillway 40 feet

Max. head on spillway 1.95 feet with .55-foot freeboard

Spillway capacity 266 sec. ft. = 319 sec. ft. per sq. mi. (See reverse side)

Estimated maximum flood flow, inflow peak = 150 sec. ft. per sq. mi. (8-hr. 10-year flood)

Outlets other than spillway 12" C.I. pipe and gate valve

Drawing filed by Howell C. Harrison, Engineer, License No. 766

It has been found that the site for the dam is suitable and the plans adequate to ensure the construction of a structure which will not be a menace to life or property. It is therefore recommended that the plans be approved and that a permit be issued, subject, however, to the following terms and conditions:—

1. That this permit does not give any property rights, either in real estate or material, nor any exclusive privileges; neither does it authorize any injury to private property nor invasion of private rights, nor any infringement of Federal, State or local laws or regulations, nor does it waive the obtaining of Federal assent, when necessary.



Form 12-12-10-48



STATE OF NEW JERSEY  
DEPARTMENT OF CONSERVATION & ECONOMIC DEVELOPMENT  
DIVISION OF WATER POLICY AND SUPPLY  
28 WEST STATE STREET  
TRENTON, NEW JERSEY

DAM APPLICATION No. \_\_\_\_\_

APPLICATION FOR PERMIT FOR CONSTRUCTION  
OR REPAIR OF DAM

Denville, Morris County, New Jersey

December 15, 1949

To the Division of Water Policy and Supply,

Gentlemen:—

In compliance with the provisions of Title 58, Chapter 4, Revised Statutes

William Wetmore, Rock Ridge Lake, Denville, Morris County, New Jersey

(Here insert name and address of public authority, private person or corporation which will be the owner of the dam)

hereby makes application for the approval of drawings and for the issuance of a permit to  
construct (reconstruct, repair) a dam known as Rock Ridge Lake Dam

(Here insert name of dam)

across Rockaway river in Morris County, New Jersey,

(Here insert name of stream)

at a point near the boundary line between Boonton Township and Berngh of Denville

(Here give location by distance from mouth of stream, county or municipal boundary or other political feature.)

for the purpose of real estate development

(Here state the purpose of the proposed lake.)

in accordance with the following information and with the complete specifications and  
drawings filed with this application and made part hereof, as follows:

Area of water shed 1.28 square miles

Maximum depth of lake 12 feet

Area of water surface 30 acres

Capacity of spillway at 2 feet head, is 400 cubic feet per second

The character of the foundation material is from observations made by excavation through  
the section of the present dam, found to be clay and large boulders.

As determined by \_\_\_\_\_

October 17, 1919

Mr. Merrill C. Harrison  
98 High Street  
Butler, New Jersey

Rock Ridge Lake Dam - Morris County

Dear Mr. Harrison:

In accordance with the promise made to you by Mr. Norman C. Hittner of this office relative to the spillway requirements for the Rock Ridge Lake Dam across a small branch of the Rockaway River in Donville, a restudy of this question has been made. By evaluating the effect of suppression by the lake upon the magnitude of flood discharge peaks, it has been determined that a broad-crested spillway having a length of 140 feet between end walls can be considered favorably by this Division, provided the minimum freeboard between spillway crest and the top of the dam is not less than 2.5 feet.

Yours very truly,

H. F. Critchlow  
Director and Chief Engineer

ECW:KES

Report on Dam Inspection

ROCK RIDGE LAKE

BRANCH OF ROCKAWAY RIVER

DENVILLE TOWNSHIP, MORRIS COUNTY

On May 29, 1947 inspection was made of the subject dam, in company with Mr. H. A. Heller, President of the Rock Ridge Community Club, and Mr. Walter Reise, member of the Board of Governors of the same club. The present dam is an earth fill dam without core wall, approximately 10 feet wide at the top. The spillway consists of an open concrete sluice 8 feet wide with notches in the upstream face of the concrete to receive flashboards. The normal water level, according to Mr. Heller, has always been maintained not over 6 inches below the top of the dam. The drainage area is <sup>34</sup> 1.4 square miles. The front of the dam was completely silted in and downstream from the dam was so completely overgrown that it was difficult to determine the exact height of the dam. However, it was estimated at approximately 8 feet.

On Sunday night, May 25, a severe cloud-burst occurred in this section of Morris County, resulting in the overtopping of the dam and washing out a section of the dam about 30 feet wide. The washed out section is approximately 30 feet distant from the sluiceway. Mr. Heller advised that all the flashboards were in at the time of the cloud-burst. At the time of this inspection trucks were already hauling in fill to close the gap in the dam, and a bulldozer was at work moving the fill and compacting same. Sand bags were being placed upstream of the gap for a width of about 6 feet and were being added as the fill was being placed. The intention is to back up the new fill with a "backstop" of rocks.

*Look  
y B-12  
page 2*

Reak Ridge Lake is one of several lakes in this region which is the center of a colony of homes, approximately 50 per cent winter and 50 per cent summer homes. The writer appreciates the urgency of making temporary repairs to this dam in order that the lake can be restored for the summer season. Therefore, the work was not ordered stopped but was permitted to proceed according to present plans, subject to confirmation from this office. Channel conditions between the dam and Rockaway River were examined and it is apparent that no damage resulted from the failure of this dam. The only house adjacent to the flood plain of the stream is the residence of F. Hamm on the northerly side of Diamond Spring Road and west of the stream. Mr. Hamm assured the writer that no damage was done to his property. The bridge over Diamond Spring Road at this point is 20 feet high, wide, with a clear opening of 4 feet above present water level and the underclearance of the bridge. Mr. Hamm stated that the Sunday night flood rose to within 3 inches of the underclearance of the bridge. It is reported that Cedar Lake dam was also overtopped but that no damage was done.

It is recommended that permission be granted for the temporary restoration of the dam as outlined above, on condition that the club will immediately engage an engineer to prepare drawings for permanent construction of the dam with adequate cutoff wall in the new fill and adequate overflow spillway capacity satisfactory to this Division. This, Mr. Heller and Mr. Reise agreed to do. Copies of the dam booklet and application blanks were left with Mr. Heller.


Trenton, N. J.  
June 2, 1917

*N. C. Wittwer*  
Norman C. Wittwer  
Hydraulic Engineer

THOMPSON-STARRETT COMPANY, INC.  
GENERAL CONTRACTORS AND BUILDERS  
444 MADISON AVENUE

NEW YORK 22, N.Y.

May 27, 1947.



Mr. H.T. Critchlow,  
Chief Engineer, Division of Water Policy Commission,  
N.J. Department of Conservation & Development,  
28 West State Street,  
Trenton, N.J.

Re. Earth Dam at Rocky Ridge Lake,  
Danville, N.J.

Dear Sir:-

On Monday morning May 26, 1947, at 9 A.M., a portion of the Earth Dam constraining the water of the Rocky Ridge Lake gave way and resulted in the following:

1. The loss of 5'-0 head of water.
2. A portion of the Dam roughly 30'-0 wide and 30'-0 long washed out.

The following method will be used to repair the break:

1. On the Lake side sand bags will be placed in such a manner as to form a base 6'-0 wide and graduating to the top of the new fill the full width of the cut.
2. On the rear side of the Dam, a back-stop of rocks 10'-0 wide, the full width of the cut will be used to hold in the fill which will consist of clay and earth. The crest of the new fill will be kept approximately 2 to 3 feet above high water mark. The full depth of the new fill in a horizontal direction will be about 30'-0.

The repair job will start under my supervision at once and unless other instructions are received from you the work will be done as outlined.

Very truly yours,

Walter R. Supt.  
Asst. Supt.

Box 186,


Denville, N.J.

APPENDIX 2


CHECK LIST

VISUAL INSPECTION

ROCK RIDGE LAKE DAM





to 1000 ft. clay




11-1-6

How much time was spent over 25 a

For 1st water, lower - 26.10








EARTH-FILL SECTION

SCALE 1 IN. = 10 FT.



17.5



*H. T. Cuthbertson*  
AM APPLICANT

440



DEVELOPMENT OF THE ROCK RIDGE LAKE AREA


# ROCK RIDGE LAKE

PLANS & PROFILES


W. C. Johnson  
Rock Ridge, N.Y.

## SECTION A-A

Scale: 1" = 100'



SECTION A-A



PLAN OF SPILLWAY  
Scale 1" = 10'

center existing

concrete sub.  
2' 0" high  
2' 0" wide  
dies 10' 0"  
masonry joint

present 100


**SPILLWAY**  
Scale

width 10' 0"

WAY

clear height 10' 0" full 10' 0"

STANDARD CONSTRUCTION AND MATERIALS



**WILLWAY DETAIL**

Scale - 1/2" = 1'



SEE MAP


SEE MAP

SEE MAP



**PLAN OF SPILLWAY**  
scale 1" = 50'

**SPILLWAY ELEVATION**  
scale 1" = 50'



**SECTION A-A**

Scale: 1" = 10'

SECTION A-A

Scale 1" = 50'

PLANS & PROFILES

FOR THE RECONSTRUCTION OF ROCK RIDGE LAKE

**ROCK RIDGE LAKE**

NEWARK MORRIS COUNTY NEW JERSEY

Scale 1" = 50'

MADE C. H. HARRISON

Prof. Engineer

Princeton N.J.



Name Dam	Rock Ridge Lake Dam	County	Morris	State New Jersey	Coordinators	NJDEP
Date(s)	Inspection May 16, 1979	Weather	Sunny	Temperature	70°	
Poel	Elevation at Time of Inspection	521.0	MSL	Tailwater at Time of Inspection	514.7	MSL

Warren Guinan	Ronald Hirschfeld
Stephen Gilman	
David Deane	

2-1

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None apparent.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None apparent.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Crest of dam is bare of vegetation because of its use as footpath. Evidence of trespassing and erosion at several locations on upstream face. Also, see "JUNCTION OF EMBANKMENT..." below.	Provide walkway surface on crest of dam. Prevent trespassing on slopes. Repair erosion and establish grassy vegetation.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Good	
RIPRAP FAILURES	No riprap.	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
RAILINGS	None	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Erosion of embankment next to right and left training walls on upstream side of spillway structure.	Repair erosion and establish grassy vegetation.
ANY NOTICEABLE SEEPAGE	Wet area at downstream toe near right abutment.	Downstream toe could not be adequately inspected because of dense growth of rose bushes and other vegetation and cover of brush, stumps, leaves, and grass clippings which have been dumped on much of downstream face near right abutment.
STAFF GAGE AND RECORDER	None apparent.	Vegetation and debris should be removed from entire embankment.
DRAINS	None apparent.	

# OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Concrete valve box good condition, only surface laitance eroded away. Steel plate cover; surface rusted only, not in place at time of inspection.	Steel cover should be put back in place.
INTAKE STRUCTURE	None.	
OUTLET PIPE	12" concrete pipe, fair condition. Surface of pipe eroded exposing aggregate.	Investigate the need for inlet valve. Outlet valve is under constant pressure.
OUTLET CHANNEL	Sand and gravel channel bottom. Trees and brush overhanging channel. Two small (6-inch) trees have fallen across channel.	Clear trees and brush 25 feet on either side of channel for a distance of 100 feet downstream from the dam. Remove trees that have blown over into channel.
EMERGENCY GATE	12" gate valve in good condition, appears to be in operable condition.	Valve should be operated periodically to prevent silting and rusting.

# UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATION'S	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Upper portion has only surface erosion to $\frac{1}{4}$ " exposing coarse aggregate. Numerous spalled areas 1" maximum depth. Lower portion constructed recently, in good condition. Abutments in good condition with minor undermining at water line.	Spalled areas should be repaired.
APPROACH CHANNEL	Wide and unobstructed.	
DISCHARGE CHANNEL	Channel has same width as spillway apron. Channel bottom is sand and gravel. Trees and brush overhanging channel. Two 6-inch trees have fallen across channel.	See "Outlet Channel" under "Outlet Works" above.
BRIDGE AND PIERS OVER SPILLWAY	Concrete pier in good condition, with minor undermining at water line. Railings and bridge deck of untreated wood are surface weathered, in fair condition. Steel bearing plate is surface rusted.	Bridge should be painted.
EXPANSION JOINTS	2 expansion joints, not sealed, compressible joint material weathered and eroded. Upper expansion joint seems to have separated approximately $\frac{1}{4}$ ".	Joints should be cleaned and rescaled.



INSTRUMENTATION		
VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None apparent.	
OBSERVATION WELLS	None apparent.	
WEIRS	None apparent.	
PIEZOMETERS	None apparent.	
OTHER	None apparent.	

# RESERVOIR

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

SLOPES

Gentle, wooded.

SEDIMENTATION

No visible evidence of  
significant sedimentation.

# DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Channel is same width as spillway apron. Trees and brush overhang channel. Two 6-inch trees have fallen across channel.	Two trees should be removed from channel.
SLOPES	Gentle to flat. Wooded.	
APPROXIMATE NO. OF HOMES AND POPULATION	Two homes, estimated population 6, located downstream of Florence Avenue.	Possible appreciable property damage. Loss of life unlikely.

CHECK LIST  
ENGINEERING DATA,  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	copy on file at New Jersey Department of Environmental Protection
REGIONAL VICINITY MAP	prepared for this report
CONSTRUCTION HISTORY	none disclosed
TYPICAL SECTIONS OF DAM	copy on file at New Jersey Department of Environmental Protection
HYDROLOGIC/HYDRAULIC DATA	on file at New Jersey Department of Environmental Protection
OUTLETS - PLAN	copy on file at New Jersey Department of Environmental Protection
- DETAILS	copy on file at New Jersey Department of Environmental Protection
- CONSTRAINTS	copy on file at New Jersey Department of Environmental Protection
- DISCHARGE RATINGS	none disclosed
RAINFALL/RESERVOIR RECORDS	none disclosed

ITEM	REMARKS
DESIGN REPORTS	copies on file at New Jersey Department of Environmental Protection
GEOLOGY REPORTS	none disclosed
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	on file at New Jersey Department of Environmental Protection none disclosed none disclosed
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	none disclosed
POST-CONSTRUCTION SURVEYS OF DAM	none disclosed
BORROW SOURCES	unknown

ITEM	REMARKS
MONITORING SERVICES	none
MODIFICATIONS	spillway repaired in 1949 concrete added to spillway in 1970's
HIGH POOL RECORDS	none disclosed
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	determination of spillway capacity for current spillway (1949) on file at New Jersey Department of Environmental Protection
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	overtopped in 1947, dam repaired and spillway replaced reports on file at New Jersey Department of Environmental Protection
MAINTENANCE OPERATION RECORDS	none disclosed

ITEM	REMARKS
SPILLWAY PLAN	
SECTIONS	copies on file at New Jersey Department of Environmental Protection
DETAILS	copies on file at New Jersey Department of Environmental Protection
OPERATING EQUIPMENT	gate valve
PLANS & DETAILS	copies on file at New Jersey Department of Environmental Protection

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: .87 square miles; wooded

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 521.1 (174 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 523.6 (215 acre-feet)

ELEVATION MAXIMUM DESIGN POOL: 524.7

ELEVATION TOP DAM: Low pt. 523.6, High pt. 525.2

CREST: free overflow concrete spillway

a. Elevation 521.1

b. Type concrete weir

c. Width 10'

d. Length 39'

e. Location Spillover approximate center of dam

f. Number and Type of Gates none

OUTLET WORKS: low-level outlet pipe

a. Type gate valve, part 12" CIP and part 12" concrete pipe

b. Location left of center of spillway

c. Entrance Inverts 515.6 (estimated)

d. Exit Inverts 514.4

e. Emergency Draindown Facilities none

HYDROMETEOROLOGICAL GAGES: none

a. Type \_\_\_\_\_

b. Location \_\_\_\_\_

c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: 579 cfs



APPENDIX 3

PHOTOGRAPHS

ROCK RIDGE LAKE DAM




17 MAY 1979

VIEW FROM LEFT SIDE OF LAKE LOOKING TOWARDS SPILLWAY



17 MAY 1979

VIEW FROM LEFT SPILLWAY ABUTMENT LOOKING AT SPILLWAY CREST  
AND SERVICE BRIDGE



17 MAY 1979

VIEW OF DOWNSTREAM CHANNEL




17 MAY 1979

VIEW UPSTREAM FROM CENTER OF SPILLWAY




17 MAY 1979

VIEW OF DOWNSTREAM FACE OF SPILLWAY SHOWING OUTLET PIPE



17 MAY 1979

VIEW LOOKING NORTHEAST ACROSS SPILLWAY APRON UPSTREAM OF  
SERVICE BRIDGE




17 MAY 1979

EROSION NEXT TO LEFT TRAINING WALL (SIMILAR EROSION AT RIGHT  
TRAINING WALL)



17 MAY 1979

VIEW OF DOWNSTREAM PORTION OF SPILLWAY LOOKING NORTHEAST



17 MAY 1979

VIEW OF VALVE BOX



17 MAY 1979

VIEW OF RETAINING WALL AT LEFT OF SPILLWAY



17 MAY 1979

VIEW LOOKING SOUTHWEST ALONG CREST OF DAM FROM RIGHT SPILLWAY  
ABUTMENT TOWARDS THE RIGHT ABUTMENT



17 MAY 1979

BRUSH AND DEBRIS ON DOWNSTREAM FACE OF DAM NEAR RIGHT ABUTMENT



17 MAY 1979

VIEW OF DENNEY POND



APPENDIX 4

HYDROLOGIC COMPUTATIONS

ROCK RIDGE LAKE DAM

Anderson-Nichols & Company, Inc.

Subject ROCK RIDGE LAKE DAM

Sheet No. 1 of 11  
Date 6/15/79  
Computed KAT  
Checked EDD

JOB NO. 3220-01

SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 3

## HYDROLOGIC COMPUTATIONS

NAME: ROCK RIDGE LAKE DAM

LOCATION: MORRIS COUNTY, NJ

DRAINAGE AREA: 87 mi<sup>2</sup>

SURFACE AREA (NORMAL POOL): 17.4 ACRES

EVALUATION CRITERIA: SIZE: SMALL  
HAZARD: SIGNIFICANT

SPILLWAY DESIGN FLOOD: BASED ON SIZE AND  
HAZARD CLASSIFICATION, THE SPILLWAY  
DESIGN FLOOD WILL BE THE 1/2 PMF (1/2 THE  
PROBABLE MAXIMUM FLOOD), WITH A PEAK  
INFLOW OF 2476 CFS.

NOTE: DRAINAGE AREA AND SURFACE AREA OF  
ROCK RIDGE LAKE WERE PLANNIMETERED DUE  
TO DISCREPANCIES IN REPORTED AREAS.  
D.A. WAS VARIOUSLY REPORTED AS 0.84 mi<sup>2</sup>  
AND 1.25 mi<sup>2</sup>; S.A. WAS VARIOUSLY REPORTED  
TO BE 20.5 ACRES AND 30 ACRES

JOB NO. 3290-01SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

DETERMINE TIME OF CONCENTRATIONREACH 1 OVERLAND FLOW, WOODED  
LENGTH = 1350'  
HEAD = 20'A. BY KIRPICH NOMOGRAPH  $T_c = 10$  minsB. BY IZZARDS FORMULA  $T_c = \frac{L_{FT}^{1.115}}{(7700)(H_{FT}^{.38})}$   
 $T_c = \frac{1350^{1.115}}{(7700)(20^{.38})} = .13 \text{ hrs} = 7.8 \text{ mins}$ 

C. BY CALIFORNIA CULVERT EQUATION

$$T_c = \left[ \frac{(11.9)(L_{mi}^3)}{H_{FT}} \right]^{.385}$$
$$= \left[ \frac{(11.9)(256^3)}{20} \right]^{.385} = .17 \text{ hrs} = 10.2 \text{ mins}$$

D. BY WESTON FORMULA  $T_c = \frac{L_{FT}}{(3600)V}$ 

WHERE V = VELOCITY

DERIVED FROM NAVY TABLE P.70 DESIGN OF SMALL DILMS

$$T_c = \frac{1350}{3600(2)} = .19 \text{ hrs} = 11.4 \text{ mins}$$

AVG  $T_c$  REACH 1 =  $(10 + 7.8 + 10.2 + 11.4) \div 4 = 9.9 \text{ mins}$ REACH 2 CHANNEL FLOW  
LENGTH = 9300'  
HEAD = 100'A. BY KIRPICH NOMOGRAPH  $T_c = 51$  minsB. BY IZZARDS FORMULA  $T_c = \frac{L_{FT}^{1.115}}{7700(H_{FT}^{.38})}$   
 $T_c = \frac{9300^{1.115}}{7700(100^{.38})} = .6 \text{ hrs} = 36 \text{ mins}$

Anderson-Nichols & Company, Inc.

Subject ROCK RIDGE

Sheet No. 3 of 11  
 Date 8/15/79  
 Computed KATE  
 Checked \_\_\_\_\_

JOB NO. 3200-01

SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

REACH 2 CONTINUED:

C BY CALIFORNIA CULVERT EQUATION:

$$T_L = \left[ \frac{11.9 (L H^3)}{H^2} \right]^{.385}$$

$$T_L = \left[ \frac{(11.9)(1.76^3)}{100} \right]^{.385} = .65 \text{ hrs} = 51 \text{ mins}$$

D. BY WESTON FORMULA:  $T_L = \frac{L \text{ FT}}{3600 (V)}$

WHERE V = VELOCITY

DERIVED FROM NAWM TABLE P. 70 DESIGN OF SMALL DAMS

$$T_L = \frac{9300}{3600(2)} = 1.3 \text{ hrs} = 78 \text{ mins}$$

$$\text{AVG } T_L \text{ REACH 2} = (51 + 36 + 51 + 78) \div 4 = 54 \text{ mins}$$

$$\begin{aligned} T_L \text{ TOTAL} &= T_L \text{ REACH 1} + T_L \text{ REACH 2} \\ &= 9.9 + 54 \\ &= \underline{\underline{63.9 \text{ mins}}} \end{aligned}$$

$$\begin{aligned} \text{LAG} &= .6 (T_L) = (.6)(63.9) = 38.3 \text{ mins} \\ &= .64 \text{ hrs} \end{aligned}$$

4 OF 11  
8/18/79  
KD

Meriden

REACH 1

REACH 2

Rockaway Valley

Private Airport

Powerville

Scott's Cem.

The Tarn

Township Sch.

Birchwood Lake

Rest Home

County

V.I.L.L.E.

D/S X-SEC #1

D/S X-SEC #2

BOUNDARY

RESTVIEW RD.

RD.

BRIDGES

Mountain

Anderson-Nichols &amp; Company, Inc.

Subject ROCK RIDGE LAKESheet No. 5 of 11Date 8/6/79Computed KDChecked EDDJOB NO. 3220-01SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29

DEVELOPMENT OF RATING CURVE

## ① SPILLWAY CURVE

A. COMPUTE Q USING WEIR FLOW EQUATION ( $Q = CLH^{3/2}$ )  
TO BEAM, THEN PRESSURE FLOW ( $Q = CA\sqrt{2gH}$ )  
FROM 522.9 TO 523.6 (BRIDGE), THEN WEIR  
FLOW EQUATION AGAIN

B. WEIR COEFFICIENT 2.64 (TAKEN FROM 1949 CULCS)  
ORIFICE COEFFICIENTS: .65 (TABLE 4-5 KING & BRATER)

C. EFFECTIVE LENGTH SPILLWAY: 39'

D. A = AREA UNDER BRIDGE = 70.2 SQ FT


E H = HEAD (FT)

## ② TOP DAM

A. COMPUTE Q USING WEIR FLOW EQUATION


B WEIR COEFFICIENT = 2.6

ELEVATION FT	SPILLWAY		TOP DAM		Q CFS	COMBINED Q CFS
	HEAD FT	Q CFS	HEAD FT	LENGTH FT		
521.1	0	0				0
521.5	.4	26				26
521.9	.8	74				74
522.3	1.2	135				135
522.7	1.6	208				208
522.9	1.8	491				491
523.3	2.2	543				543
523.6	2.5	579	0	235	0	579
524	2.9	508	1.4	235	155	663
524.9	3.8	763	1.3	235	906	1669
526	4.9	1117	2.4	225	3142	4259
528	6.9	1866	4.4	456	10,799	12,665
530	8.9	2734	6.4	650	27,363	30,097
532	10.9	3705	8.4	720	45,575	49,280

NO. 3115 R. 20 DIVISIONS PER INCH (120 DIVISIONS) BY 3 INCH CYCLES RATIO RULING.  IN STOCK DIRECT FROM CODY BOOK CO. NOTABOOD MASS. 02062  
GRAPH PAPER  
PRINTED IN U.S.A.

# ROCK RIDGE LAKE DAM COMBINED RATING CURVE 3220-01

ELEVATION  
KD  
FED  
6 OF 11



Anderson-Nichols & Company, Inc.

Subject ROCK RIDGE

Sheet No. 7 of 11  
 Date 6/14/79  
 Computed RTE  
 Checked EDD

JOB NO. 3200-01

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 1/4 IN. SCALE

## STAGE-STORAGE DETERMINATIONS


TAKE DEPTH OF LAKE TO BE 10'

ELEVATION FT	SURFACE AREA ACRES	AVG. S.A. ACRES	INCREMENTAL STORAGE AC-FT	CUMULATIVE STORAGE AC-FT
521.1	17.4	17.4	174	174
540	48.2	32.8	620	794
560	76.7	62.5	1250	2044


INPUT FOR HCC-1 (FROM CURVE)

STAGE	STORAGE
511.1	0
521.1	174
523.6	218
526	272
528	320
530	379
535	561
540	794
545	1080
550	1395
560	2044




NO 31 193 R 20 DIVISIONS PER INCH (120 DIVISIONS) BY TWO 4 1/2-INCH CYCLES RATIO RULING.  IN STOCK DIRECT FROM CODEX BOOK CO., NORWOOD, MASS. 02062  
PRINTED IN U.S.A.  
GRAPH PAPER

ROCK RIDGE LAKE DAM  
STORAGE-ELEVATION CURVE




DOWNSTREAM CROSS-SECTION NO. 2  
 1000' FROM PENNEY DAM  
 UPSTREAM OF (PROPOSED) LAKE AVE. BRIDGE



STATIONING IN FEET

# D/S CROSS-SECTION NO 1 AT DENNEY DAM



Anderson-Nichols & Company, Inc.

Subject ROCK RIDGE LAKE DAM


Sheet No. 9 of 11  
Date 6/25/79  
Computed KSE  
Checked EJ

JOB NO. 3290-01

SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

# OVERTOPPING POTENTIAL



JOB NO. 3290-01SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

DETERMINATION OF "C" FOR LOW-LEVEL OUTLET

$$D = \text{DIAMETER} = 12" \text{ CIP OR } 1.0' \text{ CIP}$$

$$N = .015 \text{ (SOIL \& WATER CONSERVATION ENGINEERING P. 632)}$$

$$A_p = \text{AREA OF PIPE OPENING} = .79 \text{ SQ. FT.}$$

$$L_p = \text{LENGTH PIPE} = 72'$$

$$K_F = \text{FRICTION LOSS THROUGH PIPE}$$

$$K_L = \text{ENTRANCE LOSS OF PIPE} = .8 \text{ (IBID P. 639)}$$

$$C_p = \text{COEFFICIENT OF DISCHARGE (INCORPORATING } A_p \& 2g)$$

$$C = \text{COEFFICIENT OF DISCHARGE}$$

$$K_F = \frac{5087 n^2}{D^{4/3}} = \frac{5087 (.015)^2}{12^{1.333}} = \frac{1.14}{27.45} = .042$$

$$C_p = A_p \sqrt{\frac{2g}{1 + K_L + K_F L_p}}$$

$$= .79 \sqrt{\frac{64.4}{1 + .8 + (.042)(72)}}$$

$$= 2.89$$

$$C = \frac{2.89}{\frac{.79}{\sqrt{64.4}}}$$

$$\therefore C = .46$$

Anderson-Nichols &amp; Company, Inc.

Subject ROCK RIDGE LAKE DAM
 Sheet No. 11 of 11  
 Date 6/26/79  
 Computed KATE  
 Checked FJD
JOB NO. 3290-01
 SQUARES  
 1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

DRAWDOWN CALCULATIONSCALCULATIONS ASSUME  $\Phi$  NO SIGNIFICANT INFLOW

② LOW LEVEL OUTLET TO BE OPERABLE

③ INVERT U/S SAME AS INVERT AT GATE = 515.6


④  $Q_p = C_p H^{1/2} = 2.89 H^{1/2}$  (SEE PREVIOUS PAGE)

⑤ AC-FT-DAY = 1.9835 (AVG Q)

⑥ DAYS =  $\Delta$  STORAGE / AC-FT-DAY

ELEV. FT.	STORAGE AG-FT	$\Delta$ STORAGE AG-FT	H FT	Q CFS	AVG Q CFS	AC-FT PER DAY	DAYS
521.1	174	10	5.5	6.78	6.62	13.13	0.76
520.6	164	10	5	6.46	6.31	12.52	0.80
520.1	154	9	4.5	6.13	5.96	11.82	0.76
519.6	145	9	4	5.78	5.60	11.11	0.81
519.1	136	9	3.5	5.41	5.21	10.33	0.87
518.6	127	9	3	5.01	4.79	9.50	0.95
518.1	118	9	2.5	4.57	4.33	8.59	1.05
517.6	109	8	2	4.09	3.82	7.58	1.06
517.1	101	8	1.5	3.54	3.22	6.39	1.25
516.6	93	8	1	2.89	2.47	4.90	1.63
516.1	85	7	.5	2.04	1.02	2.02	3.47
515.6	78		0	0			

TOTAL = 13.41



NATIONAL PROGRAM OF INSPECTION OF  
NON-FED. DAMS

ROCK RIDGE LAKE DAM  
DENVER TOWNSHIP, NEW JERSEY

REGIONAL VICINITY MAP

DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
PHILADELPHIA, PENNSYLVANIA

ANDERSON-NICHOLS & CO, INC

BOSTON, MA

SCALE IN MILES



MAP BASED ON U.S.G.S. 7.5 MINUTE QUADRANGLE  
SHEET. BOONTON, N.J., 1954, UPDATED 1970.

HEC-1 OUTPUT

OVERTOPPING ANALYSIS

ROCK RIDGE LAKE DAM



\*\*\*\*\*  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
~~DATA SAFETY OFFICER~~ JULY 1978  
LAST MODIFICATION 26 FEB 75

\*\*\*\*\*  
AT ROCK RIDGE LAKE DAM OVERTOPPING ANALYSIS - K. DOHERTY ANDERSON-NICHOLS -  
A2 NEWJERSEY DAM NUMBER 420  
A3 0.1, 0.3, 0.5, AND 1.0 MULTIPLES OF 24-HOUR PMP (SDF=0.5 PVE)

[illegible]

PREVIEW OF SEQUENCE OF STEAM NETWORK CALCULATIONS

ROUTE HYDROGRAPH TO	A1
ROUTE HYDROGRAPH TO	A2
ROUTE HYDROGRAPH TO	A3
ROUTE HYDROGRAPH TO	A4
END OF NETWORK	

JOB SPECIFICATION									
NO	NBR	MMIN	IDAY	IMR	IPW	METRC	IPRT	IPRT	INSTAN
1	0	11	0	0	0	0	0	0	0
			JCTIP	NUT	LCPT	TRACE			
			0	0	0	0			

MULTI-PLAY ANALYSES TO BE PERFORMED

```

-FLAN ANALYZES 10 BC PERFO
KFLAN=-3-NRTIC=-3 LRTIC=-1

```

RTJOS=	.20	.50	1.00
--------	-----	-----	------

[illegible]

SUB-AREA RUNOFF COMPUTATION

UPLVETOP-TNFTBY-MYDROSEPH

ISTAR	ICMP	YECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTC
01	0	0	0	0	0	1	0	0

## HYDROGRAPHIC DATA

IMT09	TARC	TRSD	TPSP	RAT	ISNC	ISNE	LOCAL
1	2	0.00	0.87	0.000	0	1	0

**PRECIP NATA**

SPER	PWS	R5	R12	R24	R48	R72	R96
0.00	22.50	113.00	122.00	125.00	0.00	0.00	0.00

**LOSS DATA**

UPOPT	STKR	DLTKR	RYJOL	EPAIN	STKRS	RTYOK	STRTL	CNSTL	ALSMX	RTIMP
0.00	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.00	0.00	0.00

UNIT HYDROGRAPH DATA

TC= 0.70 LAGE = 0.64

CESSION DATA

CTRTN= 2.00 - ORCSN= 0.00 RTICR= 1.00

UNIT HYDROGRAPH 21 END OF PERIOD CFDS,ATES, TC= 0.00 HOURS, LAC= .64 VOL= 1.00

170	48	22	16	11	7	5	4	2
170	48	22	16	11	7	5	4	2

PC.DA	HR.MN	PERIOD	RAIN	EVES	END-OF-PERIOD FLOW		PO.CA	HR.MN	PERIOD	RAIN	EXCS	LESS	CCPP C
					CCPP 0	LESS							
1.01	1.10	1	.02	0.00	.02	1.01	12.40	76	.34	.32	.02	496.	
1.01	2.20	2	.02	0.00	.02	1.01	12.50	77	.34	.32	.02	660.	
1.01	3.30	3	.02	0.00	.02	1.01	13.00	78	.34	.32	.02	795.	
1.01	4.40	4	.02	0.00	.02	1.01	13.10	79	.41	.39	.02	894.	
1.01	5.50	5	.02	0.00	.02	1.01	13.20	80	.41	.39	.02	972.	
1.01	6.00	6	.02	0.00	.02	1.01	13.30	81	.41	.39	.02	1047.	
1.01	7.10	7	.02	0.00	.02	1.01	13.40	82	.41	.39	.02	1116.	
1.01	8.20	8	.02	0.00	.02	1.01	13.50	83	.41	.39	.02	1174.	
1.01	9.30	9	.02	0.00	.02	1.01	14.00	84	.41	.39	.02	1219.	
1.01	1.40	10	.02	0.00	.02	1.01	14.10	85	.51	.49	.02	1258.	
1.01	1.50	11	.02	0.00	.02	1.01	14.20	86	.51	.49	.02	1293.	
1.01	2.00	12	.02	0.00	.02	1.01	14.30	87	.51	.49	.02	1353.	
1.01	2.10	13	.02	0.00	.02	1.01	14.40	88	.51	.49	.02	1433.	
1.01	2.20	14	.02	0.00	.02	1.01	14.50	89	.51	.49	.02	1497.	
1.01	2.30	15	.02	0.00	.02	1.01	15.00	90	.51	.49	.02	1548.	
1.01	2.40	16	.02	0.00	.02	1.01	15.10	91	.46	.45	.02	1641.	
1.01	2.50	17	.52	0.00	.02	1.01	15.20	92	.77	.76	.02	1617.	
1.01	3.00	18	.02	0.00	.02	1.01	15.30	93	1.39	1.37	.02	1731.	
1.01	3.10	19	.02	0.00	.02	1.01	15.40	94	3.48	3.46	.02	2161.	
1.01	3.20	20	.02	0.00	.02	1.01	15.50	95	1.00	.99	.02	2222.	
1.01	3.30	21	.02	0.00	.02	1.01	16.00	96	.62	.60	.02	3797.	
1.01	3.40	22	.02	0.00	.02	1.01	16.10	97	.47	.46	.02	4216.	
1.01	3.50	23	.02	0.00	.02	1.01	16.20	98	.47	.46	.02	4114.	
1.01	4.00	24	.02	0.00	.02	1.01	16.30	99	.47	.46	.02	3667.	
1.01	4.10	25	.02	0.00	.02	1.01	16.40	100	.47	.46	.02	3064.	
1.01	4.20	26	.02	0.00	.02	1.01	16.50	101	.47	.46	.02	2582.	
1.01	4.30	27	.02	0.00	.02	1.01	17.00	102	.47	.46	.02	2260.	
1.01	4.40	28	.02	0.00	.02	1.01	17.10	103	.37	.36	.02	2611.	
1.01	4.50	29	.02	0.00	.02	1.01	17.20	104	.37	.36	.02	1952.	
1.01	5.00	30	.02	0.00	.02	1.01	17.30	105	.37	.36	.02	1897.	
1.01	5.10	31	.02	0.00	.02	1.01	17.40	106	.37	.36	.02	1865.	
1.01	5.20	32	.02	0.00	.02	1.01	17.50	107	.37	.36	.02	1859.	
1.01	5.30	33	.02	0.00	.02	1.01	18.00	108	.37	.36	.02	1379.	
1.01	5.40	34	.02	0.00	.02	1.01	18.10	109	.03	.01	.02	1298.	
1.01	5.50	35	.02	0.00	.02	1.01	18.20	110	.03	.01	.02	1179.	
1.01	6.00	36	.02	0.00	.02	1.01	18.30	111	.03	.01	.02	993.	
1.01	6.10	37	.05	0.00	.05	1.01	18.40	112	.03	.01	.02	777.	
1.01	6.20	38	.05	0.00	.05	1.01	18.50	113	.03	.01	.02	572.	
1.01	6.30	39	.05	0.00	.05	1.01	19.00	114	.03	.01	.02	404.	
1.01	6.40	40	.05	0.00	.05	1.01	19.10	115	.03	.01	.02	288.	
1.01	6.50	41	.05	0.00	.05	1.01	19.20	116	.03	.01	.02	212.	
1.01	7.00	42	.05	0.00	.05	1.01	19.30	117	.03	.01	.02	160.	
1.01	7.10	43	.05	.02	.02	1.01	19.40	118	.03	.01	.02	124.	
1.01	7.20	44	.05	.03	.03	1.01	19.50	119	.03	.01	.02	100.	
1.01	7.30	45	.05	.02	.02	1.01	20.00	120	.03	.01	.02	83.	
1.01	7.40	46	.05	.03	.03	1.01	20.10	121	.03	.01	.02	71.	
1.01	7.50	47	.05	.03	.03	1.01	20.20	122	.03	.01	.02	63.	
1.01	8.00	48	.05	.03	.03	1.01	20.30	123	.03	.01	.02	58.	
1.01	8.10	49	.05	.03	.03	1.01	20.40	124	.03	.01	.02	54.	
1.01	8.20	50	.05	.03	.03	1.01	20.50	125	.03	.01	.02	52.	
1.01	8.30	51	.05	.03	.03	1.01	21.00	126	.03	.01	.02	50.	
1.01	8.40	52	.05	.03	.03	1.01	21.10	127	.03	.01	.02	49.	
1.01	8.50	53	.05	.03	.03	1.01	21.20	128	.03	.01	.02	48.	
1.01	9.00	54	.05	.03	.03	1.01	21.30	129	.03	.01	.02	48.	
1.01	9.10	55	.05	.03	.03	1.01	21.40	130	.03	.01	.02	48.	
1.01	9.20	56	.05	.03	.03	1.01	21.50	131	.03	.01	.02	48.	
1.01	9.30	57	.05	.03	.03	1.01	22.00	132	.03	.01	.02	48.	

[illegible][illegible]

ISTAG	ICOWE	IECUN	IYAFF	JULY	JFRT	INAME	ISAGE	IATLO
A?	I	n	n	n	n	I	P	O

[illegible]

ALL PLAYS HAVE SAME ROUTING DATA

CLASS	AVG	IPCS	ISAF	IMPT	IPMP	LSIN
9.000	0.00	1	1	0	0	0

14431 STS1 X A25W 5V7 1215N S215N

212	1	0	0	0.000	0.000	0.000	174.	-1
213	1	0	0	0.000	0.000	0.000	174.	-1

521.90	522.30	522.70	522.90	523.30	523.60
520.00	532.00				

527.00	74.00	126.00	208.00	451.00	543.00	575.00
--------	-------	--------	--------	--------	--------	--------

30097.00	4280.00	200.000	471.000	5430.00	571.00
----------	---------	---------	---------	---------	--------

214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466	467	468	469	470	471	472	473	474	475	476	477	478	479	480	481	482	483	484	485	486	487	488	489	490	491	492	493	494	495	496	497	498	499	500	501	502	503	504	505	506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523	524	525	526	527	528	529	530	531	532	533	534	535	536	537	538	539	540	541	542	543	544	545	546	547	548	549	550	551	552	553	554	555	556	557	558	559	560	561	562	563	564	565	566	567	568	569	570	571	572	573	574	575	576	577	578	579	580	581	582	583	584	585	586	587	588	589	590	591	592	593	594	595	596	597	598	599	600	601	602	603	604	605	606	607	608	609	610	611	612	613	614	615	616	617	618	619	620	621	622	623	624	625	626	627	628	629	630	631	632	633	634	635	636	637	638	639	640	641	642	643	644	645	646	647	648	649	650	651	652	653	654	655	656	657	658	659	660	661	662	663	664	665	666	667	66
-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	----

540.	535.	530.	525.	520.
------	------	------	------	------

• 477 •

• 927 •

• 175 •

• 555 •

• 345 •

[illegible]

1	0.0	0.0	0.0	0.0	0.0	0.0	0.0
DAM DATA							

USER DATA			
TYPEFL	CCON	EXPD	DAFWID
523.6	R.D	0.0	0.

DAM BREACH DATA	
NO.	U.
2386	0.0

PRVTD	Z	ELRP	IFAIL	WSEL	FAILEL
102	1.00	\$13.5C	5.0	321:10	350:00

UAM BREAKCH DATA

END

NO.	1.00	313.44	25.0	521.10	530.00
STATION	12	STATION	12	STATION	12

STATION A2. PLAN 14 RATIO 2

ENT-OF-PFPIOD HYDRCCGRAPH ORDINATES

[illegible]

The diagram shows a vertical arrangement of four hexagonal lattice segments. Each segment consists of a central atom (solid black circle) surrounded by six other atoms in a hexagonal pattern. The segments are connected by dashed lines, suggesting a periodic or repeating structure. The overall layout is symmetrical and represents a portion of a larger 2D crystal lattice.

1-1  
1-2  
1-3  
1-4  
1-5  
1-6

[illegible]

41.	45.	42.	40.	157.
430.	509.	510.	544.	574.
	521.	521.	552.	574.
			562.	574.

1121.	1958.	1958.	1958.
1122.	1959.	1959.	1959.
1123.	1960.	1960.	1960.
1124.	1961.	1961.	1961.
1125.	1962.	1962.	1962.
1126.	1963.	1963.	1963.
1127.	1964.	1964.	1964.
1128.	1965.	1965.	1965.
1129.	1966.	1966.	1966.
1130.	1967.	1967.	1967.
1131.	1968.	1968.	1968.
1132.	1969.	1969.	1969.
1133.	1970.	1970.	1970.
1134.	1971.	1971.	1971.
1135.	1972.	1972.	1972.
1136.	1973.	1973.	1973.
1137.	1974.	1974.	1974.
1138.	1975.	1975.	1975.
1139.	1976.	1976.	1976.
1140.	1977.	1977.	1977.
1141.	1978.	1978.	1978.
1142.	1979.	1979.	1979.
1143.	1980.	1980.	1980.
1144.	1981.	1981.	1981.
1145.	1982.	1982.	1982.
1146.	1983.	1983.	1983.
1147.	1984.	1984.	1984.
1148.	1985.	1985.	1985.
1149.	1986.	1986.	1986.
1150.	1987.	1987.	1987.
1151.	1988.	1988.	1988.
1152.	1989.	1989.	1989.
1153.	1990.	1990.	1990.
1154.	1991.	1991.	1991.
1155.	1992.	1992.	1992.
1156.	1993.	1993.	1993.
1157.	1994.	1994.	1994.
1158.	1995.	1995.	1995.
1159.	1996.	1996.	1996.
1160.	1997.	1997.	1997.
1161.	1998.	1998.	1998.
1162.	1999.	1999.	1999.
1163.	2000.	2000.	2000.
1164.	2001.	2001.	2001.
1165.	2002.	2002.	2002.
1166.	2003.	2003.	2003.
1167.	2004.	2004.	2004.
1168.	2005.	2005.	2005.
1169.	2006.	2006.	2006.
1170.	2007.	2007.	2007.
1171.	2008.	2008.	2008.
1172.	2009.	2009.	2009.
1173.	2010.	2010.	2010.
1174.	2011.	2011.	2011.
1175.	2012.	2012.	2012.
1176.	2013.	2013.	2013.
1177.	2014.	2014.	2014.
1178.	2015.	2015.	2015.
1179.	2016.	2016.	2016.
1180.	2017.	2017.	2017.
1181.	2018.	2018.	2018.
1182.	2019.	2019.	2019.
1183.	2020.	2020.	2020.
1184.	2021.	2021.	2021.
1185.	2022.	2022.	2022.
1186.	2023.	2023.	2023.
1187.	2024.	2024.	2024.
1188.	2025.	2025.	2025.
1189.	2026.	2026.	2026.
1190.	2027.	2027.	2027.
1191.	2028.	2028.	2028.
1192.	2029.	2029.	2029.
1193.	2030.	2030.	2030.
1194.	2031.	2031.	2031.
1195.	2032.	2032.	2032.
1196.	2033.	2033.	2033.
1197.	2034.	2034.	2034.
1198.	2035.	2035.	2035.
1199.	2036.	2036.	2036.
1200.	2037.	2037.	2037.
1201.	2038.	2038.	2038.
1202.	2039.	2039.	2039.
1203.	2040.	2040.	2040.
1204.	2041.	2041.	2041.
1205.	2042.	2042.	2042.
1206.	2043.	2043.	2043.
1207.	2044.	2044.	2044.

112.4	556.	421.	200.	166.	109.
520.	520.	421.	200.	166.	109.
115.	105.	98.	81.	75.	70.

	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341	2342	2343	2344	2345	2346	2347	2348	2349	2350	2351	2352	2353	2354	2355	2356	2357	2358	2359	2360	2361	2362	2363	2364	2365	2366	2367	2368	2369	2370	2371	2372	2373	2374	2375	2376	2377	2378	2379	2380	2381	2382	2383	2384	2385	2386	2387	2388	2389	2390	2391	2392	2393	2394	2395	2396	2397	2398	2399	2400	2401	2402	2403	2404	2405	2406	2407	2408	2409	2410	2411	2412	2
--	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	---

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100  
101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141  
142  
143  
144  
145  
146  
147  
148  
149  
150  
151  
152  
153  
154  
155  
156  
157  
158  
159  
160  
161  
162  
163  
164  
165  
166  
167  
168  
169  
170  
171  
172  
173  
174  
175  
176  
177  
178  
179  
180  
181  
182  
183  
184  
185  
186  
187  
188  
189  
190  
191  
192  
193  
194  
195  
196  
197  
198  
199  
200  
201  
202  
203  
204  
205  
206  
207  
208  
209  
210  
211  
212  
213  
214  
215  
216  
217  
218  
219  
220  
221  
222  
223  
224  
225  
226  
227  
228  
229  
230  
231  
232  
233  
234  
235  
236  
237  
238  
239  
240  
241  
242  
243  
244  
245  
246  
247  
248  
249  
250  
251  
252  
253  
254  
255  
256  
257  
258  
259  
260  
261  
262  
263  
264  
265  
266  
267  
268  
269  
270  
271  
272  
273  
274  
275  
276  
277  
278  
279  
280  
281  
282  
283  
284  
285  
286  
287  
288  
289  
290  
291  
292  
293  
294  
295  
296  
297  
298  
299  
300  
301  
302  
303  
304  
305  
306  
307  
308  
309  
310  
311  
312  
313  
314  
315  
316  
317  
318  
319  
320  
321  
322  
323  
324  
325  
326  
327  
328  
329  
330  
331  
332  
333  
334  
335  
336  
337  
338  
339  
340  
341  
342  
343  
344  
345  
346  
347  
348  
349  
350  
351  
352  
353  
354  
355  
356  
357  
358  
359  
360  
361  
362  
363  
364  
365  
366  
367  
368  
369  
370  
371  
372  
373  
374  
375  
376  
377  
378  
379  
380  
381  
382  
383  
384  
385  
386  
387  
388  
389  
390  
391  
392  
393  
394  
395  
396  
397  
398  
399  
400  
401  
402  
403  
404  
405  
406  
407  
408  
409  
410  
411  
412  
413  
414  
415  
416  
417  
418  
419  
420  
421  
422  
423  
424  
425  
426  
427  
428  
429  
430  
431  
432  
433  
434  
435  
436  
437  
438  
439  
440  
441  
442  
443  
444  
445  
446  
447  
448  
449  
450  
451  
452  
453  
454  
455  
456  
457  
458  
459  
460  
461  
462  
463  
464  
465  
466  
467  
468  
469  
470  
471  
472  
473  
474  
475  
476  
477  
478  
479  
480  
481  
482  
483  
484  
485  
486  
487  
488  
489  
490  
491  
492  
493  
494  
495  
496  
497  
498  
499  
500  
501  
502  
503  
504  
505  
506  
507  
508  
509  
510  
511  
512  
513  
514  
515  
516  
517  
518  
519  
520  
521  
522  
523  
524  
525  
526  
527  
528  
529  
530  
531  
532  
533  
534  
535  
536  
537  
538  
539  
540  
541  
542  
543  
544  
545  
546  
547  
548  
549  
550  
551  
552  
553  
554  
555  
556  
557  
558  
559  
560  
561  
562  
563  
564  
565  
566  
567  
568  
569  
570  
571  
572  
573  
574  
575  
576  
577  
578  
579  
580  
581  
582  
583  
584  
585  
586  
587  
588  
589  
590  
591  
592  
593  
594  
595  
596  
597  
598  
599  
600  
601  
602  
603  
604  
605  
606  
607  
608  
609  
610  
611  
612  
613  
614  
615  
616  
617  
618  
619  
620  
621  
622  
623  
624  
625  
626  
627  
628  
629  
630  
631  
632  
633  
634  
635  
636  
637  
638  
639  
640  
641  
642  
643  
644  
645  
646  
647  
648  
649  
650  
651  
652  
653  
654  
655  
656  
657  
658  
659  
660  
661  
662  
663  
664  
665  
666  
667  
668  
669  
670  
671  
672  
673  
674  
675  
676  
677  
678  
679  
680  
681  
682  
683  
684  
685  
686  
687  
688  
689  
690  
691  
692  
693  
694  
695  
696  
697  
698  
699  
700  
701  
702  
703  
704  
705  
706  
707  
708  
709  
710  
711  
712  
713  
714  
715  
716  
717  
718  
719  
720  
721  
722  
723  
724  
725  
726  
727  
728  
729  
730  
731  
732  
733  
734  
735  
736  
737  
738  
739  
740  
741  
742  
743  
744  
745  
746  
747  
748  
749  
750  
751  
752  
753  
754  
755  
756  
757  
758  
759  
760  
761  
762  
763  
764  
765  
766  
767  
768  
769  
770  
771  
772  
773  
774  
775  
776  
777  
778  
779  
780  
781  
782  
783  
784  
785  
786  
787  
788  
789  
790  
791  
792  
793  
794  
795  
796  
797  
798  
799  
800  
801  
802  
803  
804  
805  
806  
807  
808  
809  
810  
811  
812  
813  
814  
815  
816  
817  
818  
819  
820  
821  
822  
823  
824  
825  
826  
827  
828  
829  
830  
831  
832  
833  
834  
835  
836  
837  
838  
839  
840  
84

[illegible]

[illegible]

PEAK OUTFLOW IS 2022. AT TIME 16.33 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	2,622	865	284	234	3519
CFS	57	24	7	7	94
INCHES		9.25	10.43	10.43	10.43
AC-FT		264.27	264.23	264.23	264.23
THOUS CU M		425	484	484	484
		520	597	597	597



THE NAM PREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .021 HOURS DURING PREACH FORMATION.  
 DOWNSTREAM CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS.  
 THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPLETED PREACH HYDROGRAPH.  
 INTERMEDIATE FLOWS ARE INTERPOLATED FROM END-OF-PREACH VALUES.

TIME OF PREACH HYDROGRAPH (HOURS)	TIME FROM DEFINING PREACH HYDROGRAPH (HOURS)	INTERPOLATED PREACH HYDROGRAPH (CFS)	COMPLETED PREACH HYDROGRAPH (CFS)	ERROR (CFS)	ACCUMULATED ERROR (CFS)	ACCUMULATED ERROR (ACFT)
15.000	0.000	595	595	0	0	0
15.021	.021	608	622	14	14	0
15.042	.042	622	636	14	28	0
15.063	.063	636	650	14	42	0
15.084	.084	650	664	14	56	0
15.104	.104	664	678	14	70	0
15.125	.125	678	692	14	84	0
15.146	.146	692	706	14	98	0
15.167	.167	706	720	14	112	0
15.188	.188	720	734	14	126	0
15.209	.209	734	748	14	140	0
15.229	.229	748	762	14	154	0
15.250	.250	762	776	14	168	0
15.271	.271	776	790	14	182	0
15.292	.292	790	804	14	196	0
15.313	.313	804	818	14	210	0
15.333	.333	818	832	14	224	0
15.354	.354	832	846	14	238	0
15.375	.375	846	860	14	252	0
15.396	.396	860	874	14	266	0
15.417	.417	874	888	14	280	0
15.438	.438	888	902	14	294	0
15.458	.458	902	916	14	308	0
15.479	.479	916	930	14	322	0
15.500	.500	930	944	14	336	0
15.521	.521	944	958	14	350	0
15.542	.542	958	972	14	364	0
15.563	.563	972	986	14	378	0
15.583	.583	986	1000	14	392	0
15.604	.604	1000	1014	14	406	0
15.625	.625	1014	1028	14	420	0
15.646	.646	1028	1042	14	434	0
15.667	.667	1042	1056	14	448	0
15.688	.688	1056	1070	14	462	0
15.709	.709	1070	1084	14	476	0
15.729	.729	1084	1098	14	490	0
15.750	.750	1098	1112	14	504	0
15.771	.771	1112	1126	14	518	0
15.792	.792	1126	1140	14	532	0
15.813	.813	1140	1154	14	546	0
15.833	.833	1154	1168	14	560	0
15.854	.854	1168	1182	14	574	0
15.875	.875	1182	1196	14	588	0
15.896	.896	1196	1210	14	602	0
15.917	.917	1210	1224	14	616	0
15.938	.938	1224	1238	14	630	0
15.958	.958	1238	1252	14	644	0
15.979	.979	1252	1266	14	658	0
16.000	1.000	1266	1280	14	672	0



STATION A2

(4) POINTS AT NORMAL TIME INTERVAL

(CO) INTERPLATED REACH HYDROGRAPH

TIME

[illegible]





STATION 25+ PLAN 25 P110 2 (BREACH)

OUTFLOW

STAGE

PEAK

6-HOUR

24-HOUR

72-HOUR

TOTAL VOLUME

MAXIMUM STAGE IS

319.4

MAXIMUM STORAGE IS

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

20.

[illegible]

## STATION 44, PLAN 1, RATIO 2, CONTINUED (NO BREACH)

[illegible][illegible]

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	1924.	862.	244.	234.		35072.
CMS	54.	24.	7.	7.		993.
INCHES		9.22	10.42	10.42		10.42
AC-FT		234.20	264.58	264.58		264.58
THOUS. CU Y.		42R.	483.	483.		483.
		527.	596.	596.		596.

MAXIMUM STAGE IS 505.6  
MAXIMUM STORAGE = 12.0

## A49 PLAN 29 3710 2

[illegible][illegible][illegible]

	YEAR	6-HOUR	7-8-HOUR	7-9-HOUR	TOTAL VOLUME
F.S.	2102	1037	301	289	4394
M.C.	60	29	6	6	1227
C.S.		1781	1287	1287	1287
M		20-31	326.99	326.99	326.99
F		504	597	597	597
J		697	736	736	736

**MAXIMUM STORAGE = 13.**

U.S. 51 39412 William

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE FEET (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIOS APPLIED TO FLOWS

20 50 100

HYDROGRAPH AT A1 .87 1 843. 2100. 4216.

2 2.25 2 843. 2100. 4216.

3 2.25 3 843. 2100. 4216.

ROUTED TO A2 .87 1 594. 2022. 4118.

2 2.25 2 16.83 57.63 116.62

3 3.38 3 50.34 110.04 3966.

ROUTED TO A3 .87 1 591. 1971. 4019.

2 2.25 2 16.72 55.82 113.60

3 3.38 3 50.34 109.39 3883.

ROUTED TO A4 .87 1 598. 1974. 4026.

2 2.25 2 16.83 57.63 114.01

3 3.38 3 50.34 107.56 3839.

PLAN 1 ..... INITIAL VALUE SPILLWAY CREST TOP OF DAM

WITHOUT BREACH ELEVATION 521.10 521.10 523.68

STORAGE 174. 174. 218.

OUTFLOW 0. 0. 579.

RATIO OF RESERVOIR MAXIMUM DEPTH OVER DAM MAXIMUM STORAGE AC-FT

20 521.67 .07 220. 594. .50 16.67 0.00

50 525.05 1.35 251. 2022. 4.00 16.33 0.00

100 525.44 2.34 271. 4118. 6.00 16.33 0.00

PLAN 2 ..... INITIAL VALUE SPILLWAY CREST TOP OF DAM

WITH BREACH ELEVATION 521.10 521.10 523.68

STORAGE 174. 174. 218.

OUTFLOW 0. 0. 579.

RATIO OF RESERVOIR MAXIMUM DEPTH OVER DAM MAXIMUM STORAGE AC-FT

20 523.66 .06 210. 1232. .44 17.50 16.50

50 525.78 1.38 225. 2131. 2.75 16.50 15.00

100 526.78 1.38 247. 3086. 2.38 14.50 13.50



# WITHOUT BREACH

PLAN 1	STATION	AS	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
RATIO					
.20			171.	517.5	16.50
.50			1971.	519.3	16.50
1.00			4019.	520.9	16.50

# WITH BREACH

PLAN 2	STATION	AS	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
RATIO					
.20			1123.	518.4	17.67
.50			2093.	519.4	16.33
1.00			3863.	520.7	16.50

# WITHOUT BREACH

PLAN 1	STATION	AA	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
RATIO					
.20			582.	503.7	17.00
.50			1924.	505.6	16.50
1.00			4026.	507.4	16.50

# WITH BREACH

PLAN 2	STATION	AA	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
RATIO					
.20			1124.	504.6	17.67
.50			2102.	505.6	16.23
1.00			3792.	507.2	16.50

APPENDIX 5

REFERENCES

ROCK RIDGE LAKE DAM

## APPENDIX 5

### REFERENCES

#### ROCK RIDGE LAKE DAM

1. King, H. W., and E. F. Brater, Handbook of Hydraulics, McGraw-Hill Book Co., New York, Fifth Edition, 1963.
2. New Jersey Department of Environmental Protection Files, "Dams in New Jersey - Reference Date" Dam Number 440.
3. Robinson Aerial Surveys, Inc., Newton, N.J., Photogrammetric Mapping, Scale 1:1200, Contour Interval 2 Feet (1963).
4. Schwab, G. O., R. K. Frevert, T. W. Edminster, and K. K. Barnes, Soil and Water Conservation Engineering, the Ferguson Foundation Agricultural Engineering Series, John Wiley and Sons, Inc., New York, 1966, 683 pp.
5. U.S. Department of Commerce, Weather Bureau, "Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24 and 48 Hours," Hydrometeorological Report No. 33, Washington, April 1956.
6. United States Department of the Interior, Bureau of Reclamation, Design of Small Dams, U.S. Government Printing Office, Washington 1977, 816 pp.
7. United States Department of the Interior, Geological Survey, 7.5 Minute Series (Topographic) Maps, Scale 1:24,000, Contour Interval 20 Feet: Boonton, N.J., (1954).